

Work Order ID 74610

Monday, October 03, 2011 4:03:50 PM



Page 1

Item ID:	D3161-9	Accept		Setup	Start	
Revision ID:						
Item Name:	Hinge 17.0"				Stop	
Start Date:	10/3/2011	Start Qty:	6.00			
Required Date:	10/5/2011	Req'd Qty:	6.00			
Reference:						

Approvals:	Process Plan:		Date:	11-10-11	Tooling:		Date:		Run	Start	
	QC:		Date:		SPC (Y/N):		Date:			Stop	

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D3161	Rev A2								

100		0.00							
	Small Fab								
Small Fab	Memo	0.00							
Small Fab	(1) 72" Hinge makes (4) D3161-9 parts at 17" long <input type="checkbox"/> Cut to length as per Dwg D3161								

11/10/05 (6)

110	QC5- Inspect part completeness to step on W/O	0.00							
QC	Memo	0.00							
Quality Control									

(6)

120	Identify as per dwg & Stock Location	0.00							
Packaging	Memo	0.00							
Packaging									

(6) SP 11-10-11

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 74610

Monday, October 03, 2011 4:03:50 PM



Page 2

Item ID: D3161-9

Accept



Setup Start



Revision ID:

Stop



Item Name: Hinge 17.0"

Start Date: 10/3/2011 Start Qty: 6.00



Cust Item ID:

Required Date: 10/5/2011 Req'd Qty: 6.00



Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

130

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

11/10/11

R11-10-11

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Monday, October 03, 2011 4:03:55 PM

Page 1

Work Order ID: 74610

Parent Item: D3161-9

Parent Item Name: Hinge 17.0"



Start Date: 10/3/2011

Required Date: 10/5/2011

Start Qty: 6.00

Required Qty: 6.00

Comments: IPP ☐ A ☐ 04.08.24 ☐ New Issue ☐ KJ/JLM ☐

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MS20257-3-7200 Piano Hinge		Purchased	No			100	f	40.3759	1.65	9.9			

Location

Loc Qty

Loc Code

ST449

0.00778948

116817

0.00778948

ST489A

40.36811

117543

2.126

118686

38.24211

Handwritten signature
9.9

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries




DESIGN #	DRAWN BY #	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED RF	APPROVED #	DRAWING NO. D3161	REV. A SHEET 1 OF 1
DATE 02.04.24		TITLE HINGE	SCALE NTS
A	02.04.24	NEW ISSUE	
A1	04.02.27	ADDED D3161-5	
A2	04.06.30	ADD D3161-7 & D3161-9	

RELEASED
02.04.24

P/N	LENGTH 'L'	DESCRIPTION
D3161-1	13.5"	HINGE (REPLACES MS20257-3-13.5 ON D2183)
D3161-3	15.0"	HINGE (REPLACES MS20257-3-15.0 ON D2950-041)
D3161-5	9.9"	HINGE
D3161-7	14.0"	HINGE
D3161-9	17.0"	HINGE

74610

11-10-4



NOTES:

- ① MAKE FROM MS20257-3-7200 HINGE

Copyright © 2002 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries